Department of Purchasing & Contract Compliance

Fulton County, GA

BID TABULATION SHEET
PROJECT NAME: AUTOMOBILE REPAIR SERVICES – SOUTH FULTON

PROJECT NUMBER: 11ITB78594YB-TR
DATE: June 14, 2011
TOTAL NUMBER OF BIDDERS: 2

Terrence Reese
Assistant Purchasing Agent

CONTRACTOR'S NAME	BID BOND YES/NO	TOTAL BASE BID AMOUNT	GA UTILITY LICENSE ON OUTSIDE ENVELOPE YES/NO
ALIGNMENT & FRAME SERVICES	N/A	$85,714.75	N/A
GORDON'S AUTOMOTVE REPAIR SERVICE CENTER	N/A	$67,388.00	N/A

THE RESULTS RECEIVED IN RESPONSE TO THIS SOLICITATION DOES NOT REFLECT AWARD OF THIS CONTRACT. RESPONSES WILL BE FURTHER EVALUATED BY FULTON COUNTY EPRESENTATIVES.

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 1

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED													NON RESPONSIVE VENDORS AND OTHER INFORMATION
	VENDOR CODE			CONTACT		CONTACT		CONTACT		CONTACT			
	VC0000108718			VS0000017759		VENDOR CODE		VENDOR CODE		VENDOR CODE			
	VENDOR NAME			VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME			
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE									
	ADDRESS			ADDRESS		ADDRESS		ADDRESS		ADDRESS			
	2441 NORTH MAIN STREET EAST POINT, GEORGIA 30344			1450 DONNELLY ATLANTA, GEORGIA 30310									
	TELEPHONE:			TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE			
	(404) 7671516			(404) 758-6801									
	CONTACT: Management			CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:			
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL		
Alternator, patrol vehicles- 180 amp minimum:	1	$328.90	$ 328.90	$ 350.00	$ 350.00		$ -		$ -		$ -		
Alternator, all other vehicles-highest amperage available	1		$ -	$ 250.00	$ 250.00		$ -		$ -		$ -		
Brake Service- Front Wheels: 2005-2010 Ford Crown Vic:													
A) Replace pads, turn rotors and labor:	1	$193.09	$ 193.09	$ 140.00	$ 140.00		$ -		$ -		$ -		
B) Replace pads, replace rotors and labor:	1	$325.93	$ 325.93	$ 260.00	$ 260.00		$ -		$ -		$ -		
C) Replace pads, replace rotors, replace calipers and labor:	1	$496	$ 496.39	$ 360.00	$ 360.00		$ -		$ -		$ -		
Brake Service- Rear Wheels: 2005-2010 Ford Crown Vic													
A) Replace pads, turn rotors and labor:	1	$183.20	$ 183.20	$ 140.00	$ 140.00		$ -		$ -		$ -		
B) Replace pads, replace rotors and labor:	1	$ 273.04	$ 273.04	$ 260.00	$ 260.00		$ -		$ -		$ -		
C) Replace pads, replace rotors, replace calipers and labor:	1	$ 429.65	$ 429.65	$ 360.00	$ 360.00		$ -		$ -		$ -		
Brake Service- Front Wheels: 2003-2004 Ford Crown Vic													
A) Replace pads, turn rotors and labor:	1	$ 193.09	$ 193.09	$ 140.00	$ 140.00		$ -		$ -		$ -		
B) Replace pads, replace rotors and labor:	1	$ 326.03	$ 326.03	$ 260.00	$ 260.00		$ -		$ -		$ -		
C) Replace pads, replace rotors, replace calipers and labor:	1	$ 539.49	$ 539.49	$ 360.00	$ 360.00		$ -		$ -		$ -		

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 2

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED												NON RESPONSIVE VENDORS AND OTHER INFORMATION
	VENDOR CODE			VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE		
	VC0000108718			VS0000017759								
	VENDOR NAME			VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME		
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE								
	ADDRESS			ADDRESS		ADDRESS		ADDRESS		ADDRESS		
	2441 NORTH MAIN STREET EAST			1450 DONNELLY								
	TELEPHONE:			TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE		
	(404) 7671516			(404) 758-6801								
	CONTACT: Management			CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:		
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	
Brake Service- Rear Wheels: 2003-2004 Ford Crown Vic												
A) Replace pads, turn rotors and labor:	1	$178.88	$ 178.88	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$268.72	$ 268.72	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$425.36	$ 425.36	$ 360.00	$ 360.00		$ -		$ -		$ -	
Brake Service- Front Wheels: 1993-2002 Ford Crown Vic												
A) Replace pads, turn rotors and labor:	1	$350	$ 350.08	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$389.90	$ 389.90	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$489.50	$ 489.50	$ 360.00	$ 360.00		$ -		$ -		$ -	
Brake Service- Rear Wheels: 1993-2002 Ford Crown Vic												
A) Replace pads, turn rotors and labor:	1	$ 193.45	$ 193.45	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$ 281.41	$ 281.41	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$ 426.99	$ 426.99	$ 360.00	$ 360.00		$ -		$ -		$ -	
Brake Service-Front Wheels: 2003 Dodge Intrepid												
A) Replace pads, turn rotors and labor:	1	$ 171.00	$ 171.00	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$ 298.80	$ 298.80	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$ 460.76	$ 460.76	$ 360.00	$ 360.00		$ -		$ -		$ -	

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 3

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED												NON RESPONSIVE VENDORS AND OTHER INFORMATION
	VENDOR CODE			VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE		
	VC0000108718			VS0000017759								
	VENDOR NAME			VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME		
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE								
	ADDRESS			ADDRESS		ADDRESS		ADDRESS		ADDRESS		
	2441 NORTH MAIN STREET EAST			1450 DONNELLY								
	TELEPHONE:			TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE		
	(404) 7671516			(404) 758-6801								
	CONTACT: Management			CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:		
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	
Brake Service- Rear Wheels: 2003 Dodge Intrepid												
A) Replace pads, turn rotors and labor:	1	$160.31	$ 160.31	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$229.41	$ 229.41	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$402.09	$ 402.09	$ 360.00	$ 360.00		$ -		$ -		$ -	
Brake Service- Front Wheels: 2010 Chevrolet Impala												
A) Replace pads, turn rotors and labor:	1	$169	$ 169.06	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$289.38	$ 289.38	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$423.10	$ 423.10	$ 360.00	$ 360.00		$ -		$ -		$ -	
Brake Service- Rear Wheels: 2010 Chevrolet Impala												
A) Replace pads, turn rotors and labor:	1	$ 166.64	$ 166.64	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$ 242.94	$ 242.94	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$ 427.50	$ 427.50	$ 360.00	$ 360.00		$ -		$ -		$ -	
Brake Service- Front Wheels: All other vehicles												
A) Replace pads, turn rotors and labor:	1	$ 193.99	$ 193.99	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1	$ 317.99	$ 317.99	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1	$ 529.99	$ 529.99	$ 360.00	$ 360.00		$ -		$ -		$ -	

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 4

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED												NON RESPONSIVE VENDORS AND OTHER INFORMATION
	CONTACT											
	VENDOR CODE			VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE		
	VC0000108718			VS0000017759								
	VENDOR NAME			VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME		
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE								
	ADDRESS			ADDRESS		ADDRESS		ADDRESS		ADDRESS		
	2441 NORTH MAIN STREET EAST			1450 DONNELLY								
	TELEPHONE:			TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE		
	(404) 7671516			(404) 758-6801								
	CONTACT: Management			CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:		
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	
Brake Service - Rear Wheels: All other vehicles												
A) Replace pads, turn rotors and labor:	1		$ -	$ 140.00	$ 140.00		$ -		$ -		$ -	
B) Replace pads, replace rotors and labor:	1		$ -	$ 260.00	$ 260.00		$ -		$ -		$ -	
C) Replace pads, replace rotors, replace calipers and labor:	1		$ -	$ 360.00	$ 360.00		$ -		$ -		$ -	
Oil Change, 10W-30, five (5) quarts and filter												
(Time required)	1	$33	$ 32.50	$ 19.99	$ 19.99		$ -		$ -		$ -	
10W-30 oil, per quart	1	$3.24	$ 3.24	$ 3.80	$ 3.80		$ -		$ -		$ -	
Oil Change, 10W-40, five (5) quarts and filter												
(Time required)	1	$ 32.50	$ 32.50	$ 19.99	$ 19.99		$ -		$ -		$ -	
10W-40 oil, per quart	1	$ 3.24	$ 3.24	$ 3.80	$ 3.80		$ -		$ -		$ -	
Oil Change, 5W-30, five (5) quarts and filter												
(Time required)	1	$ 32.50	$ 32.50	$ 19.99	$ 19.99		$ -		$ -		$ -	
5W-30 oil, per quart	1	$ 3.24	$ 3.24	$ 3.80	$ 3.80		$ -		$ -		$ -	
Oil Change, 5W-20, five (5) quarts and filter												
(Time required)	1	$ 32.50	$ 32.50	$ 19.99	$ 19.99		$ -		$ -		$ -	
5W-20 oil, per quart	1	$ 3.24	$ 3.24	$ 3.80	$ 3.80		$ -		$ -		$ -	
Oil Change, 20W-50, five (5) quarts and filter												
(Time required)	1	$ 32.50	$ 32.50	$ 19.99	$ 19.99		$ -		$ -		$ -	
20W-50 oil, per quart	1	$ 3.24	$ 3.24	$ 3.80	$ 3.80		$ -		$ -		$ -	
Lube												
(Time required)	1	$ 32.50	$ 32.50	$ 5.00	$ 5.00		$ -		$ -		$ -	

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 5

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED													NON RESPONSIVE VENDORS AND OTHER INFORMATION
	VENDOR CODE			VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE			
	VC0000108718			VS0000017759									
	VENDOR NAME			VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME			
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE									
	ADDRESS			ADDRESS		ADDRESS		ADDRESS		ADDRESS			
	2441 NORTH MAIN STREET EAST			1450 DONNELLY									
	TELEPHONE:			TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE			
	(404) 7671516			(404) 758-6801									
	CONTACT: Management			CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:			
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL		
Tune - Up (8 Cylinder)	1	$230.00	$ 230.00	$ 250.00	$ 250.00		$ -		$ -		$ -		
(6 Cylinder)	1	$215.00	$ 215.00	$ 250.00	$ 250.00		$ -		$ -		$ -		
(4 Cylinder)	1	$195.00	$ 195.00	$ 250.00	$ 250.00		$ -		$ -		$ -		
Tire service													
Rotate and balance, 4 wheels	1	$72.84	$ 72.84	$ 32.00	$ 32.00		$ -		$ -		$ -		
Mount and balance tire, replace valve stem	1	$30	$ 29.95	$ 17.50	$ 17.50		$ -		$ -		$ -		
Wheel Alignment													
Two (2) wheels	1	$49.95	$ 49.95	$ 65.00	$ 65.00		$ -		$ -		$ -		
Four (4) wheels	1	$ 69.95	$ 69.95	$ 65.00	$ 65.00		$ -		$ -		$ -		
Windshield Wiper Replacement	1	$ 17.14	$ 17.14	$ 10.00	$ 10.00		$ -		$ -		$ -		
Battery (850 CCA, high output), installed	1	$ 115.70	$ 115.70	$ 120.00	$ 120.00		$ -		$ -		$ -		
Radiator Service							$ -		$ -		$ -		
Flush System and New Coolant	1	$ 115.00	$ 115.00	$ 35.00	$ 35.00		$ -		$ -		$ -		
Radiator Replacement													
Remove old radiator and install remanufactured replacement Parts and labor	1	$ 221.00	$ 221.00	$ 200.00	$ 200.00		$ -		$ -		$ -		
Warranty period for remanufactured radiator		6 months		1 year			$ -		$ -		$ -		
Transmission							$ -		$ -		$ -		
Transmission Service w/Filter	1	$ 57.95	$ 57.95	$ 75.00	$ 75.00		$ -		$ -		$ -		
Flush transmission system	1	$ 60.05	$ 60.05	$ 750.00	$ 750.00		$ -		$ -		$ -		
Transmission Rebuild													
Remove transmission, rebuild and re-install Parts and labo	1	$ 1,515.00	$ 1,515.00	$ 1,899.00	$ 1,899.00		$ -		$ -		$ -		
Warranty period		1 year		1 year			$ -		$ -		$ -		

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 6

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED												NON RESPONSIVE VENDORS AND OTHER INFORMATION
		VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE		
		VC0000108718		VS0000017759								
		VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME		
		ALIGNMENT & FRAME SERVICES, INC.		GORDON'S AUTOMOTIVE SERVICE								
		ADDRESS		ADDRESS		ADDRESS		ADDRESS		ADDRESS		
		2441 NORTH MAIN STREET EAST		1450 DONNELLY								
		TELEPHONE:		TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE		
		(404) 7671516		(404) 758-6801								
		CONTACT: Management		CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:		
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	
Transmission exchange												
Remove inoperative transmission from vehicle "A"												
Remove transmission from vehicle "B" and install in vehicle "A"												
Labor	1	$1,430.00	$ 1,430.00	$ 900.00	$ 900.00		$ -		$ -		$ -	
Rear-End Rebuild												
Remove rear-end, rebuild and re-install Parts and labor	1	$1,400	$ 1,400.00	$ 650.00	$ 650.00		$ -		$ -		$ -	
Warranty period		6 months		1 year			$ -		$ -		$ -	
Rear-End Exchange												
Remove rear-end from vehicle "A"												
Remove rear-end from vehicle "B" and install in vehicle "A"												
Labor	1	$ 2,145.00	$ 2,145.00	$ 650.00	$ 650.00		$ -		$ -		$ -	
Remanufactured Engine												
Remove engine and install remanufactured replacement Parts and labor	1	$ 3,194.50	$ 3,194.50	$ 2,300.00	$ 2,300.00		$ -		$ -		$ -	
Warranty period for remanufactured engine		1 year		1 year			$ -		$ -		$ -	
Engine exchange												
Remove engine from vehicle "A"												
Remove engine from vehicle "B" and install in vehicle "A"												
Labor	1	$ 780.00	$ 780.00	$ 900.00	$ 900.00		$ -		$ -		$ -	

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 7

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED												NON RESPONSIVE VENDORS AND OTHER INFORMATION
	VENDOR CODE			VENDOR CODE		VENDOR CODE		VENDOR CODE		VENDOR CODE		
	VC0000108718			VS0000017759								
	VENDOR NAME			VENDOR NAME		VENDOR NAME		VENDOR NAME		VENDOR NAME		
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE								
	ADDRESS			ADDRESS		ADDRESS		ADDRESS		ADDRESS		
	2441 NORTH MAIN STREET EAST			1450 DONNELLY								
	TELEPHONE:			TELEPHONE		TELEPHONE		TELEPHONE		TELEPHONE		
	(404) 7671516			(404) 758-6801								
	CONTACT: Management			CONTACT: Fernando Gordon		CONTACT:		CONTACT:		CONTACT:		
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL	
Water pump replacement												
Remove water pump and install remanufactured replacement Parts and labor	1	$243.60	$ 243.60	$ 200.00	$ 200.00		$ -		$ -		$ -	
Warranty period for remanufactured water pump		1 year		1 year			$ -		$ -		$ -	
Intake replacement												
Remove intake and install replacement Parts and labor	1	$824.53	$ 824.53	$ 850.00	$ 850.00		$ -		$ -		$ -	
Warranty period for replacement intake												
Exhaust system												
Replace tail pipe- parts and labor	1	$253.50	$ 253.50	$ 60.00	$ 60.00		$ -		$ -		$ -	
Replace muffler- parts and labor	1	$ 489.19	$ 489.19	$ 100.00	$ 100.00		$ -		$ -		$ -	
Replace catalytic converter- parts and labor	1	$ 997.51	$ 997.51	$ 300.00	$ 300.00		$ -		$ -		$ -	
Coil pack, installed-parts and labor	1	$ 54.60	$ 54.60	$ 125.00	$ 125.00		$ -		$ -		$ -	
Ignition coil, installed-parts and labor	1		$ -	$ 125.00	$ 125.00		$ -		$ -		$ -	
Air conditioning compressor												
AC compressor installed w/ refrigerant	1	$ 793.60	$ 793.60	$ 510.00	$ 510.00		$ -		$ -		$ -	

BID TAB

BID NUMBER/QUOTE #: 11 ITB78594YB-TR | OPENING DATE: 06/14/2011 | PAGE NUMBER: 8

BID DESCRIPTION: **AUTOMOBILE REPAIR SERVICES-SOUTH FULTON**

REQUESTING DEPARTMENT: POLICE

DESCRIPTION OF PRODUCT OR SERVICES DESIRED														NON RESPONSIVE VENDORS AND OTHER INFORMATION
	CONTACT					CONTACT			CONTACT			CONTACT		
	VENDOR CODE			VENDOR CODE		VENDOR CODE			VENDOR CODE			VENDOR CODE		
	VC0000108718			VS0000017759										
	VENDOR NAME			VENDOR NAME		VENDOR NAME			VENDOR NAME			VENDOR NAME		
	ALIGNMENT & FRAME SERVICES, INC.			GORDON'S AUTOMOTIVE SERVICE										
	ADDRESS			ADDRESS		ADDRESS			ADDRESS			ADDRESS		
	2441 NORTH MAIN STREET EAST			1450 DONNELLY										
	TELEPHONE:			TELEPHONE		TELEPHONE			TELEPHONE			TELEPHONE		
	(404) 7671516			(404) 758-6801										
	CONTACT:			CONTACT:		CONTACT:			CONTACT:			CONTACT:		
	Management			Fernando Gordon										
	QTY	UNIT $	TOTAL	UNIT $	TOTAL	UNIT $	TOTAL		UNIT $	TOTAL		UNIT $	TOTAL	
Labor Charge:														
Monday through Friday, normal business hours:	1	$65.00	$ 65.00	$ 50.00	$ 50.00		$ -			$ -			$ -	
Monday through Friday, after hours:	1	$65.00	$ 65.00	$ 50.00	$ 50.00		$ -			$ -			$ -	
Saturday, normal business hours:	1	$75.00	$ 75.00	$ 50.00	$ 50.00		$ -			$ -			$ -	
Saturday, after hours:	1	$75.00	$ 75.00	$ 50.00	$ 50.00		$ -			$ -			$ -	
Sunday (if applicable):	1	$85.00	$ 85.00	N/A			$ -			$ -			$ -	
Discount:														
Parts and service items will be provided at the following percentage discount from retail price schedule:		130%		10%			$ -			$ -			$ -	
GRAND TOTAL:			$26,922.82		$21,732.45					$0.00			$0.00	

BIDS MAILED	63	NO RESPONSE: 61	ASSISTANT PURCHASING AGENT:	Terrence Reese	6/14/2011
BIDS RECEIVED:	2	NO-BIDS: 0	CHIEF ASSISTANT:	William Long	6/14/2011
			DEPT. AUTHORIZATION:		